

**SIL 3308-11 Service Information Letter
SN3308 Electronic Horizontal Situation Indicator**

Date: August 08, 2013

Regarding: Unapproved Lamp Kits for SN3308

SIL Revision: A – Initial Notification

Reason

To alert users of the SN3308 EHSI of the existence of unapproved and potentially unsafe lamp replacement kits.

Applicability

Applies to all variants of the SN3308.

Description

Sandel Avionics has discovered that unapproved lamp replacement kits are being sold by unauthorized third parties. These lamps are unapproved, potentially unsafe, and are not authorized by Sandel Avionics for installation in the SN3308. Sandel Avionics is the only source for approved lamp replacement kits. Any entity found to be offering unapproved lamp replacement kits should be brought to the attention of Sandel Avionics and should be reported to the FAA using form 8120-11 "Suspected Unapproved Parts Report".

Sandel Avionics has approved lamp replacement kits for the SN3308 available at a very reasonable cost. Please contact Sandel Product Support at 760-727-4900 for assistance with ordering.

End