

## **SB 4550-03 SA4550 Primary Attitude Display Service Bulletin**

---

Date: October 31, 2008  
Regarding: SA4550 1.06 Software Release  
Revision: A, Initial Release

### **Reason**

Availability of new SA4550 Software to correct RADAR Altimeter selection input pins.

### **Applicability**

Applies to Sandel part number SA4550-0xx with 1.05 software or earlier and interfaced with either ARINC 552 or ALT 50 RADAR Altimeters.

### **Description**

Although there are no known applicable installations, Sandel is publishing this service bulletin and software update version 1.06 to correct this issue.

This new release of software provides the following changes:

- Corrects reversal of RADAR Altimeter selection pins on connector J2 pins K and L.

In accordance with the SA4550 Component Maintenance Manual, document number 82010-0133, revision A, SB 4550-03 related files including the software and update utility can be accessed on the Sandel website at:

[www.sandel.com/SA4550\\_sup\\_sb.php](http://www.sandel.com/SA4550_sup_sb.php) [case-sensitive]

or you can contact Sandel Product Support at (760)727-4900 selection "2"

Update the existing Pilot's Guide, document number 82010-PG with the updated "Effectivity, Errata and Revision History" page, document number 82010-ERR revision D1.

# SANDEL®

## **Compliance**

On condition; otherwise recommended.

## **Warranty**

On condition 1 Hour; No warranty for recommended.

## **Documentation**

82010-PG-ERR Revision D1 Pilot's Guide Effectivity page

**End**