

SIL 3453H-02 Service Information Letter **ST3453H HeliTAWS™**

Date: March 11, 2016
Regarding: ST3453H HeliTAWS Software Version A1.06
SIL Revision: A – Initial Notification

Reason

At high internal temperatures, the display is automatically dimmed in increments to aid in cooling. This may cause the display to flicker.

Applicability

Applies to Sandel part number ST3400H-9XXX with MOD A (Serial numbers 50-1048 and above)

Description

Software version A1.06 has the following change:

- The display brightness adjustment increment in response to high temperature is reduced to avoid flickering

Compliance

Optional

Warranty Reimbursement

N/A

Manpower

1 hour

Approval

This modification does not affect the original approval. Contact Sandel for details if needed.

Identification

MOD A on data label

Testing

None