

## **SB 3400-31 Service Bulletin ST3400 TAWS**

---

Date: April 24, 2014

Regarding: Failure of the ST3400 to receive GPS serial port communication during initialization.

SB Revision: A – Initial Notification

### **Reason**

Sandel has received a customer report that the ST3400 could fail to receive GPS serial communication during power up of the GPS and the ST3400. The problem is related to the sequence in which the units initialize. When the failure occurs, “GPWS FAIL” is displayed on the screen and the Pilot’s Menu messages will indicate “FMS1 NO DATA”. The problem will persist until power to the ST3400 is reset.

### **Applicability**

On condition only.

This Service Bulletin does not apply to operators that do not have this problem.

### **Description**

Software versions A3.14 and B3.14 have been released to correct this issue.

### **Compliance**

Recommended

### **Warranty**

Not applicable

### **Documentation**

82002-PG-ERR-F2

**END**