

## **SB 3400-12-A, Service Bulletin (Mandatory)**

---

Date: April 15, 2008  
Regarding: ST3400 version A3.12 Software  
SB Revision: A – Initial Release

### **Reason**

ST3400 with software version A3.12 may unintentionally activate the RMI display mode.

### **Applicability**

ST3400 TAWS with A3.12 version software. The applicable TAWS units were shipped from the factory between March 11 and March 31, 2008 as new or factory repaired for return to service.

The software version can be determined by viewing the ST3400 display screen during power up.

### **Description**

The ST3400 changes to the RMI display mode without user input. TAWS alerting is not affected.

### **Compliance**

Mandatory within 50 hours:

Load the ST3400 with software version A3.13.

SB 3400-12 related files including the software, installation instructions, and update utility can be accessed on the Sandel website at:

[www.sandel.com/ST3400\\_TAWS\\_sup\\_sb.php](http://www.sandel.com/ST3400_TAWS_sup_sb.php) [case-sensitive]

or you can contact Sandel Product Support at (760)727-4900 ext. "2"

### **Warranty Reimbursement**

1 hour

**Manpower**

1 hour.

**Approval**

This modification does not affect the original approval.

**Identification**

No change

**Testing**

None

**Documentation**

Not applicable

**END**