

SB 4500-06-B, Service Bulletin (Mandatory)

Date: April 18, 2008
Regarding: SN4500 interfaced with WSI Datalink Weather Receiver
SB Revision: B – Revised, new SN4500 software version 1.04.

Reason

Due to a change in WSI weather data, unpredictable operation of the SN4500 may result with software versions prior to 1.04.

Applicability

All SN4500 Primary Navigation Displays with WSI weather display activated.

Description

The bounding GEO reference position coordinates and data size for NOWrad weather product was inadvertently changed by WSI Corporation.

Compliance

Mandatory as soon as practical:

Load the SN4500 with software version 1.04.

SB 4500-06 related files including the software, installation instructions, and update utility can be accessed on the Sandel website at:

www.sandel.com/SN4500_sup_sb.php [case-sensitive]

or you can contact Sandel Product Support at (760)727-4900 ext. "2"

Warranty Reimbursement

None

Manpower

1.0 hour

Approval

This modification does not affect the original approval.

Identification

No change

Testing

None

Documentation

82009-PG-ERR-B2

END