

SB 4500-05-B, Service Bulletin (Mandatory)

Date: April 18, 2008
Regarding: SN4500 version 1.03 Software
SB Revision: B – Availability of software version 1.04

Reason

Two aircraft operators have reported SN4500 resetting during ground and flight operations after loading SN4500 software version 1.03.

Applicability

All SN4500 Primary Navigation Displays.

Description

The SN4500 display resets and then recovers after approximately 10 seconds. Sandel has verified this occurrence and has released version 1.04 correcting this problem.

Compliance

Mandatory as soon as practical:

1. Load the SN4500 with software version 1.04.
2. If applicable, remove the previous placed placard, "INTEG annunciator not available on EHSI".

SB 4500-06 related files including the software, installation instructions, and update utility can be accessed on the Sandel website at:

www.sandel.com/SN4500_sup_sb.php [case-sensitive]

or you can contact Sandel Product Support at (760)727-4900 ext. "2"

Warranty Reimbursement

1 hour

Manpower

1 hour.

Approval

This modification does not affect the original approval.

Identification

No change

Testing

None

Documentation

82009-PG-ERR-B2

END