SANDEL®

SIL 3453H-03   Service Information Letter
ST3453H HeliTAWS™

Date: June 7, 2018

Regarding: ST3453H HeliTAWS Software Version A1.08

SIL Revision: B – Software version was originally A1.07

Reason

A customer reported a case where the terrain in either REL or TOPO mode at times would be rendered in gray. This may occur only when using the combination of ARC View and 10nm range and the rendered display exceeds the terrain data currently in memory. As the aircraft moves and new terrain data is loaded into memory the issue self corrects.

TAWS alerting is not affected.

Applicability

Applies to Sandel part number ST3400H-9XXX with MOD A (Serial numbers 50-1048 and above)

Description

Software version A1.08 has the following change:
- Change to terrain display processing to correct issue

Compliance

Recommended

Warranty Reimbursement

N/A

Manpower

1 hour

Approval

This modification does not affect the original approval. Contact Sandel for details if needed.

Identification

MOD A on data label

SANDEL®

Testing

None

Documentation

82050-PG-ERR   Rev. B5   Pilot's Guide Errata

END