

SIL 3308-12 Service Information Letter SN3308 Electronic Horizontal Situation Indicator

Date: April 02, 2014

Regarding: Replacement Windows SIL Revision: B – Final Notification

Reason

Applicability

Applies to all variants of the SN3308.

Description

Due to parts unavailability, replacement windows for the SN3308 are no longer available.

End

SIL_3308-12-B.doc Page 1 of 1