

SIL 3308- 08 Service Information Letter

Date: August 27, 2008
Regarding: SN3308 operating with GPS WAAS
Revision: A, Initial Release

Reason

To notify SN3308 users of new software update version 2.30.

Applicability

SN3308 installed with a GPS WAAS receiver using ARINC 429 interface.

Description

When installed with a GPS WAAS receiver using ARINC 429 interface, the SN3308 with version 2.30 software will support GPS vertical guidance, "Integrity" annunciation and selected approach annunciators.

With this software update installed and using an ARINC 429 GPS receiver, it is no longer required to use the analog interface connections for GPS vertical guidance or external discrete annunciations.

Contact the Sandel Sales Order desk at akugler@sandel.com or (760) 727-4900 ext. 1491 to purchase this software update.

This software update requires Sandel SN3308 Loader version 2.50.

Compliance

Optional

Warranty Reimbursement

None

Manpower

Variable

Approval

This modification does not affect the original approval.

Identification

No change

Testing

Refer to ground test section of SN3308 Navigation Display Installation Manual Document 90106-IM Revision J.

Documentation

Sandel Documents:

90106-IM revision J, SN3308 Installation Manual

82001-PG-ERR-2.30, SN3308 Pilots Guide Effectivity and Errata

END