

SIL3500-08 Service Information Letter

Date: 08/20/2008

Regarding: Typographical error on TSO Nameplate

Reason

Voltage shown on TSO nameplate shows incorrect maximum voltage.

Applicability

Applies to Sandel part number SN3500-xxx, serial numbers as follows:

Lamp backlight units: Serial numbers 2000 and lower. LED backlight units: Serial numbers 5-2200 and lower.

Description

Maximum voltage shown on TSO nameplate incorrectly shows 30.3 VDC. The nameplate should read 33 VDC.

Compliance

This Service Information Letter is for informational purposes only. No action is required and there is no change to the certification basis.

Warranty

Not applicable.

Documentation

Not applicable.

END

SIL3500-08.doc Page 1 of 1