

## **SB 3500-07-B, Service Bulletin (Mandatory)**

---

Date: April 18, 2008  
Regarding: SN3500 interfaced with WSI Datalink Weather Receiver  
SB Revision: B – Revised, new SN3500 software version 3.03.

### **Reason**

Due to a change in WSI weather data, unpredictable operation of the SN3500 may result with software versions prior to 3.03.

### **Applicability**

All SN3500 Primary Navigation Displays with WSI weather display activated.

### **Description**

The bounding GEO reference position coordinates and data size for NOWrad weather product was inadvertently changed by WSI Corporation.

### **Compliance**

Mandatory as soon as practical:

Load the SN3500 with software version 3.03.

SB 3500-07 related files including the software, installation instructions, and update utility can be accessed on the Sandel website at:

[www.sandel.com/SN3500\\_sup\\_sb.php](http://www.sandel.com/SN3500_sup_sb.php) [case-sensitive]

or you can contact Sandel Product Support at (760)727-4900 ext. "2"

### **Warranty Reimbursement**

None

### **Manpower**

1.0 hour

### **Approval**

This modification does not affect the original approval.

**Identification**

No change

**Testing**

None

**Documentation**

82005-PG-ERR-F1

**END**